



# WINSTON'S CHIMNEY SERVICE



2701 S. Oakland St.  
Arlington, VA 22206  
Tel. 703-379-5008

VA HIC #27917

"We Are Committed To Excellence"


- Type of Fireplace  Prefab  Masonry
- Woodstove  Insert  Freestanding
- No. of Fireplaces \_\_\_\_\_ • No. of Stories \_\_\_\_\_
- Last Cleaned \_\_\_\_\_ • Height \_\_\_\_\_ ft.
- Flue Size: Fireplace \_\_\_\_\_  
Furnace \_\_\_\_\_

Customer Lawrence (Ricky) Turner Vent Connector Size \_\_\_\_\_ Furnace \_\_\_\_\_  
 Address 9011 GIBBETOWN PIKE Water Heater \_\_\_\_\_  
 City GA State VA Zip 22066 • BTU Input \_\_\_\_\_ Furnace \_\_\_\_\_  
 Phone 2035-0999 Water Heater \_\_\_\_\_  
 Date 11-6-98

- 1.) Furnace Flue
- 2.) Fireplace Flue
- 3.) Crown
- 4.) Stainless Steel Cap
- 5.) Flashing
- 6.) Smoke Chamber
- 7.) Firebox
- 8.) Ash Pit
- 9.) Thimble
- 10.) Damper
- 11.) Clean Out Door
- 12.) Brick Work

## CONDITION REPORT / COMMENTS

LIFETIME WARRANTY ON CAP  
10yr warranty on masonry work



CHECK # 623

### CUSTOMER VERIFICATION

I HAVE READ THIS FORM AND NOW UNDERSTAND WHICH AREAS OF MY HEATING AND VENTING SYSTEMS APPEAR TO BE SATISFACTORY AND WHICH AREAS ARE NOT  
 Signed \_\_\_\_\_ Date \_\_\_\_\_

### NEXT SERVICING RECOMMENDED

In \_\_\_\_\_ of \_\_\_\_\_ year

The National Fire Protection Agency recommends that Fireplaces and Chimneys should be inspected annually for structural faults.

Sweep or Mason's Signature A. Owens

### RECEIPT / INVOICE

| DESCRIPTION                 | PRICE        |                 |
|-----------------------------|--------------|-----------------|
| <u>Crown</u>                |              | <u>425 EACH</u> |
| <u>2 SWEEP</u>              |              | <u>79 EACH</u>  |
| <u>CAP 4 TOTAL</u>          |              | <u>99 EACH</u>  |
|                             | <u>TOTAL</u> | <u>1,404</u>    |
| PAYMENT DUE UPON COMPLETION |              |                 |
|                             | <u>PAID</u>  | <u>500</u>      |
| <u>BALANCE</u>              | <u>TOTAL</u> | <u>904</u>      |



# WINSTON'S CHIMNEY SERVICE



2701 S. Oakland St.  
Arlington, VA 22208  
Tel. 703-379-5008


VA HIC #27917

"We Are Committed To Excellence"

Customer RIDLEY  
Address 9011 GEORGETOWN PIKE  
City GF State VA Zip 22066  
Phone REGINA LAWRENCE 757-0944  
Date 11-05-99

- Type of Fireplace  Prefab  Masonry
- Woodstove  Insert  Freestanding  \_\_\_\_\_
- No. of Fireplaces \_\_\_\_\_ • No. of Stories \_\_\_\_\_
- Last Cleaned \_\_\_\_\_ • Height \_\_\_\_\_ ft.
- Flue Size: Fireplace \_\_\_\_\_  
Furnace \_\_\_\_\_
- Vent Connector Size Furnace \_\_\_\_\_  
Water Heater \_\_\_\_\_
- BTU Input Furnace \_\_\_\_\_  
Water Heater \_\_\_\_\_

- 1.) Furnace Flue
- 2.) Fireplace Flue
- 3.) Crown
- 4.) Stainless Steel Cap
- 5.) Flashing
- 6.) Smoke Chamber
- 7.) Firebox
- 8.) Ash Pit
- 9.) Thimble
- 10.) Damper
- 11.) Clean Out Door
- 12.) Brick Work



## CONDITION REPORT / COMMENTS

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

## CUSTOMER VERIFICATION

I HAVE READ THIS FORM AND NOW UNDERSTAND WHICH AREAS OF MY HEATING AND VENTING SYSTEMS APPEAR TO BE SATISFACTORY AND WHICH AREAS ARE NOT.  
Signed \_\_\_\_\_ Date \_\_\_\_\_

## NEXT SERVICING RECOMMENDED

In \_\_\_\_\_ of \_\_\_\_\_ year  
season year  
The National Fire Protection Agency recommends that Fireplaces and Chimneys should be inspected annually for structural faults.

Sweep or Mason's Signature A. HOLLOWAY

## RECEIPT / INVOICE

| DESCRIPTION  | PRICE               |
|--|---------------------|
| RELINING OF INSERT STOVE TO TERMINATION HEIGHT OF CHIMNEY (DOWNSTAIRS) | 27.99 <sup>00</sup> |
| PICK-UP AND INSTALLATION OF STOVE                                      | 450 <sup>00</sup>   |
| PAYMENT DUE UPON COMPLETION  |                     |
| TOTAL  | 3249 <sup>00</sup>  |
| PAID CHECK # 4776  |                     |

